AQUIFER TEST ANALYSIS

Big Sandy Energy Project
Wikieup, Mohave County, Arizona

Prepared for
URS Corporation
Stanford Place 3
4582 South Ulster Street
Denver, Colorado 80237

DS&A

David Schafer & Associates
9955 North 101st Street
Stillwater, Minnesota 55082

REPORT

November 2000

DS&A
David Schafer & Associates

Aquifer Test Analysis

Big Sandy Energy Project
Wikieup, Mohave County, Arizona

TABLE OF CONTENTS

Introduction 1

Time Drawdown and Recovery Data 2

Pumping Test 3

Distance Drawdown Data 4

Early-Time Response 5

Late-Time Response 6

Aquifer Extent 7

Linear Fracture Analysis 9

Interconnection of Aquifers 10

No Porosity Data 13

Conclusions 14

FIGURES

1. PW2 Drawdown
2. OW2 Drawdown
3. OW3 Drawdown
4. OW4 Drawdown
5. PW2 Recovery – Complete Data Set
6. PW2 Recover – Expanded Scale
7. OW2 Recovery
8. OW3 Recovery

FIGURES, Continued

9. OW4 Recovery

10. Distance Versus Calculated Recovery After 9.82 Days

11. Log-Log Plot of OW2 Recovery

12. Log-Log Plot of OW3 Recovery

13. Log-Log Plot of OW4 Recovery

14. Linear Plot of OW2 Drawdown

15. Linear Plot of OW3 Drawdown

16. Linear Plot of OW4 Drawdown

17. Linear Plot of OW2 Recovery

18. Linear Plot of OW3 Recovery

19. Linear Plot of OW4 Recovery

20. Estimated Area of Volcanic Aquifer

21. Linear Analysis of OW2 Drawdown

22. Linear Analysis of OW3 Drawdown

23. Linear Analysis of OW4 Drawdown

24. Hydrograph for Harris Well

25. Hydrograph for OW1

26. Hydrograph for Salazar Well